

Piper PA-31T, Bulkhead STA 49.6 Repair

- Repair of fatigue cracks on nose landing gear bulkhead of Piper Cheyenne II
- Minor Repair design under privileges of AeroFEM Design Organisation Approval
- Repair design and certification by AeroFEM
- Fabrication of repair parts and installation by a designated maintenance organisation

