

Piper PA-31T, Engine Nacelle Bulkhead Repair

- Repair of fatigue cracks on engine nacelle bulkhead of Piper Cheyenne II
- Minor Repair design under privileges of AeroFEM Design Organisation Approval
- Repair design and certification by AeroFEM
- Fabrication of repair parts and installation by a designated maintenance organisation

